

Detailed Inventory					
Village of Broadview - PWS ID NO: IL-0310300					
Date Last Updated:				11/22/2024	
Total Number of Services:	2,869	Total # of Lead Services (Private Side):	951	Total # of Confirmed Lead Services (Public Side):	0
		Total # of Unknown Services (Private Side):	96	Total # of Unknown Services (Public Side):	1,598

Unique Service Line ID	Lead and Copper Sample Site #	Street Address			High-Risk or Sensitive Population? (Yes/No)	Classification of Entire Service	Was a Lead Service Line Previously Replaced at this Location?	Material of Service Line Replacement	Is Service Line newly Identified Since Last Submitted Inventory?	System-Owned Portion (Main to B-Box)							Customer-Owned Portion (B-Box to Meter)				
										System-Owned Portion (Main to B-Box) Service Line Material Classification	Service Line Installation Date	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field Verified:		Customer-Owned Portion Service Line Material Classification	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field Verified:		
														Describe the Field Verification Method	Enter the Date of Field Verification				Describe the Field Verification Method	Enter the Date of Field Verification	
1	N/A	1700	FILLMORE	STREET	No	Non-Lead	Yes - Other	Copper	Yes - Other	Non-Lead - Copper	Sep-24	Installation date after lead ban	Yes	Other	9/1/2024	Copper	Installation date after lead ban	Yes	Other	Sep-24	
2	N/A	1704	FILLMORE	STREET	No	Non-Lead	Yes - Other	Copper	Yes - Other	Non-Lead - Copper	Sep-24	Installation date after lead ban	Yes	Other	9/1/2024	Copper	Installation date after lead ban	Yes	Other	Sep-24	
3	LP1C015	2227	10TH	AVENUE	No	Lead	No	N/A	No	Lead	Unknown	Other	No	Other		Lead	Other	Yes	Visual inspection at the meter pit	2019	
4	LP1C017	2223	10TH	AVENUE	No	Lead	No	N/A	No	Lead	Unknown	Other	No			Lead		Yes	Visual inspection at the meter pit	2019	
1	N/A	2219	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
2	N/A	2231	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
3	N/A	2235	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
4	N/A	2239	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
5	N/A	2243	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
6	N/A	2251	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
7	N/A	2300	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
8	N/A	2305	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
9	N/A	2308	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
10	N/A	2312	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
11	N/A	2316	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
12	N/A	2320	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
13	N/A	2321	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
14	N/A	2324	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
15	N/A	2328	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
16	N/A	2329	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
17	N/A	2332	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
18	N/A	2333	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
19	N/A	2336	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
20	N/A	2337	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
21	N/A	2340	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
22	N/A	2341	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
23	N/A	2344	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
24	N/A	2401	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
25	N/A	2412	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
26	N/A	2413	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
27	N/A	2417	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
28	N/A	2501	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
29	N/A	2532	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
30	N/A	2537	10TH	AVENUE	Yes - Day Care	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
31	N/A	2544	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
32	N/A	2929	10TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
33	LP1C008	2532	11TH	AVENUE	No	Lead	No	N/A	No	Lead	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
34	LP1C033	2445	11TH	AVENUE	No	Lead	No	N/A	No	Lead	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
35	N/A	2218	11TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
36	N/A	2226	11TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
37	N/A	2234	11TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
38	N/A	2246	11TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
39	N/A	2301	11TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
40	N/A	2305	11TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
41	N/A	2309	11TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
42	N/A	2313	11TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
43	N/A	2316	11TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
44	N/A	2321	11TH	AVENUE	No	Lead	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	























































Unique Service Line ID	Lead and Copper Sample Site #	Street Address			High-Risk or Sensitive Population? (Yes/No)	Classification of Entire Service	Was a Lead Service Line Previously Replaced at this Location?	Material of Service Line Replacement	Is Service Line newly Identified Since Last Submitted Inventory?	System-Owned Portion (Main to B-Box)						Customer-Owned Portion (B-Box to Meter)					
										System-Owned Portion (Main to B-Box) Service Line Material Classification	Service Line Installation Date	Basis of Material Classification		Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field Verified:		Customer-Owned Portion Service Line Material Classification	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field Verified:	
												Describe the Field Verification Method	Enter the Date of Field Verification		Describe the Field Verification Method	Enter the Date of Field Verification					
1341	N/A	2805	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
1342	N/A	2808	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
1343	N/A	2809	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
1344	N/A	2813	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1345	N/A	2816	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1346	N/A	2817	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
1347	N/A	2820	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1348	N/A	2821	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
1349	N/A	2824	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
1350	N/A	2825	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1351	N/A	2828	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
1352	N/A	2829	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1353	N/A	2832	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1354	N/A	2833	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
1355	N/A	2836	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1356	N/A	2837	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1357	N/A	2840	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1358	N/A	2841	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
1359	N/A	2844	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1360	N/A	2845	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1361	N/A	2900	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1362	N/A	2901	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
1363	N/A	2904	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1364	N/A	2905	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1365	N/A	2908	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1366	N/A	2909	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1367	N/A	2912	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
1368	N/A	2913	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
1369	N/A	2917	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
1370	N/A	2921	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
1371	N/A	2925	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1372	N/A	2931	10TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1373	N/A	2222	11TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1374	N/A	2230	11TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Unknown - Material Unknown		No			
1375	N/A	2238	11TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1376	N/A	2242	11TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
1377	N/A	2250	11TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1378	N/A	2300	11TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Unknown - Material Unknown		No			
1379	N/A	2310	11TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1380	N/A	2317	11TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
1381	N/A	2324	11TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
1382	N/A	2332	11TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Unknown - Material Unknown		No			
1383	N/A	2340	11TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
1384	N/A	2341	11TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Lead	Other	Yes	Visual inspection at the meter pit	2019	
1385	N/A	2404	11TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1386	N/A	2417	11TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Unknown - Material Unknown		No			
1387	N/A	2420	11TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1388	N/A	2425	11TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1389	N/A	2429	11TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	















Unique Service Line ID	Lead and Copper Sample Site #	Street Address			High-Risk or Sensitive Population? (Yes/No)	Classification of Entire Service	Was a Lead Service Line Previously Replaced at this Location?	Material of Service Line Replacement	Is Service Line newly Identified Since Last Submitted Inventory?	System-Owned Portion (Main to B-Box)						Customer-Owned Portion (B-Box to Meter)					
										System-Owned Portion (Main to B-Box) Service Line Material Classification	Service Line Installation Date	Basis of Material Classification		Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field Verified:		Customer-Owned Portion Service Line Material Classification	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field Verified:	
												Describe the Field Verification Method	Enter the Date of Field Verification		Describe the Field Verification Method	Enter the Date of Field Verification					
1714	N/A	2046	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
1715	N/A	2100	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Unknown - Material Unknown		No			
1716	N/A	2101	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
1717	N/A	2104	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1718	N/A	2109	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1719	N/A	2110	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1720	N/A	2113	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
1721	N/A	2116	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1722	N/A	2117	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1723	N/A	2121	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1724	N/A	2124	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1725	N/A	2125	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1726	N/A	2132	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1727	N/A	2204	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1728	N/A	2208	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1729	N/A	2212	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	No	Visual inspection at the meter pit	2019	
1730	N/A	2218	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1731	N/A	2222	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized		No	Visual inspection at the meter pit	2019	
1732	N/A	2230	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Unknown - Material Unknown		No			
1733	N/A	2301	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized		No	Visual inspection at the meter pit	2019	
1734	N/A	2309	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Unknown - Material Unknown		No			
1735	N/A	2317	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Unknown - Material Unknown		No			
1736	N/A	2321	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized		No	Visual inspection at the meter pit	2019	
1737	N/A	2345	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
1738	N/A	2400	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1739	N/A	2417	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1740	N/A	2421	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1741	N/A	2429	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1742	N/A	2433	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
1743	N/A	2505	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1744	N/A	2508	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Unknown - Material Unknown		No			
1745	N/A	2509	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1746	N/A	2516	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1747	N/A	2517	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1748	N/A	2520	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1749	N/A	2529	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1750	N/A	2533	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1751	N/A	2541	14TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
1752	N/A	1800	15TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1753	N/A	1801	15TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1754	N/A	1803	15TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1755	N/A	1830	15TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
1756	N/A	1832	15TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1757	N/A	1833	15TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Unknown - Material Unknown		No			
1758	N/A	1841	15TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1759	N/A	1845	15TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1760	N/A	1846	15TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper		No	Visual inspection at the meter pit	2019	
1761	N/A	1900	15TH	AVENUE	No	Unknown	No	N/A	Yes - Other	Unknown - Material Unknown	2006	Installation record (e.g., tap card)	Yes			Iron	Other	Yes	Visual inspection at the meter pit	2019	
1762	N/A	1903	15TH	AVENUE	No	Unknown	No	N/A	Yes - Other	Unknown - Material Unknown	2006	Installation record (e.g., tap card)	Yes			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
1763	N/A	1944	15TH	AVENUE	No	Unknown	No	N/A	Yes - Other	Unknown - Material Unknown	2006	Installation record (e.g., tap card)	Yes			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
1764	N/A	2000	15TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Unknown - Material Unknown		No			
1765	N/A	2001	15TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1766	N/A	2008	15TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
1767	N/A	2009	15TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper		No	Visual inspection at the meter pit	2019	







Unique Service Line ID	Lead and Copper Sample Site #	Street Address			High-Risk or Sensitive Population? (Yes/No)	Classification of Entire Service	Was a Lead Service Line Previously Replaced at this Location?	Material of Service Line Replacement	Is Service Line newly Identified Since Last Submitted Inventory?	System-Owned Portion (Main to B-Box)						Customer-Owned Portion (B-Box to Meter)				
										System-Owned Portion (Main to B-Box) Service Line Material Classification	Service Line Installation Date	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field Verified:		Customer-Owned Portion Service Line Material Classification	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field Verified:	
														Describe the Field Verification Method	Enter the Date of Field Verification				Describe the Field Verification Method	Enter the Date of Field Verification
1930	N/A	2030	17TH	AVENUE	No	Unknown	No	N/A	Yes - Other	Non-Lead - Copper	1998	Installation record (e.g., tap card)	Yes			Galvanized	Other	Yes	Visual inspection at the meter pit	2019
1931	N/A	2217	17TH	AVENUE	No	Unknown	No	N/A	Yes - Other	Non-Lead - Copper	1998	Installation record (e.g., tap card)	Yes			Galvanized	Other	Yes	Visual inspection at the meter pit	2019
1932	N/A	2246	17TH	AVENUE	No	Unknown	No	N/A	Yes - Other	Non-Lead - Copper	1998	Installation record (e.g., tap card)	Yes			Unknown - Material Unknown		No		
1933	N/A	2308	17TH	AVENUE	No	Unknown	No	N/A	Yes - Other	Non-Lead - Copper	1998	Installation record (e.g., tap card)	Yes			Galvanized		No	Visual inspection at the meter pit	2019
1934	N/A	2321	17TH	AVENUE	No	Unknown	No	N/A	Yes - Other	Non-Lead - Copper	1998	Installation record (e.g., tap card)	Yes			Galvanized		No	Visual inspection at the meter pit	2019
1935	N/A	2415	17TH	AVENUE	No	Unknown	No	N/A	Yes - Other	Non-Lead - Copper	1998	Installation record (e.g., tap card)	Yes			Unknown - Material Unknown		No		
1936	N/A	2445	17TH	AVENUE	No	Unknown	No	N/A	Yes - Other	Non-Lead - Copper	1998	Installation record (e.g., tap card)	Yes			Galvanized	Other	Yes	Visual inspection at the meter pit	2019
1937	N/A	2700	17TH	AVENUE	No	Unknown	No	N/A	Yes - Other	Non-Lead - Copper	1998	Installation record (e.g., tap card)	Yes			Unknown - Material Unknown		No		
1938	N/A	2812	17TH	AVENUE	No	Unknown	No	N/A	Yes - Other	Non-Lead - Copper	1998	Installation record (e.g., tap card)	Yes			Unknown - Material Unknown		No		
1939	N/A	1000	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019
1940	N/A	1020	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019
1941	N/A	1100	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019
1942	N/A	1120	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019
1943	N/A	1140	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019
1944	N/A	1160	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019
1945	N/A	1938	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019
1946	N/A	1941	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019
1947	N/A	2001	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019
1948	N/A	2002	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019
1949	N/A	2003	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019
1950	N/A	2004	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019
1951	N/A	2006	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019
1952	N/A	2008	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019
1953	N/A	2011	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019
1954	N/A	2012	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019
1955	N/A	2013	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019
1956	N/A	2015	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019
1957	N/A	2017	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019
1958	N/A	2018	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019
1959	N/A	2019	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019
1960	N/A	2020	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019
1961	N/A	2021	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019
1962	N/A	2024	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019
1963	N/A	2026	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019
1964	N/A	2027	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019
1965	N/A	2029	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019
1966	N/A	2031	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019
1967	N/A	2103	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	No	Visual inspection at the meter pit	2019
1968	N/A	2108	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019
1969	N/A	2109	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019
1970	N/A	2112	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019
1971	N/A	2114	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019
1972	N/A	2116	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019
1973	N/A	2117	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019
1974	N/A	2118	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019
1975	N/A	2122	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019
1976	N/A	2218	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019
1977	N/A	2219	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019
1978	N/A	2227	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Unknown - Material Unknown		No		
1979	N/A	2230	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019
1980	N/A	2231	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019
1981	N/A	2235	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Unknown - Material Unknown		No		
1982	N/A	2238	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	No	Visual inspection at the meter pit	2019
1983	N/A	2239	18TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019



Unique Service Line ID	Lead and Copper Sample Site #	Street Address			High-Risk or Sensitive Population? (Yes/No)	Classification of Entire Service	Was a Lead Service Line Previously Replaced at this Location?	Material of Service Line Replacement	Is Service Line newly Identified Since Last Submitted Inventory?	System-Owned Portion (Main to B-Box)							Customer-Owned Portion (B-Box to Meter)				
										System-Owned Portion (Main to B-Box) Service Line Material Classification	Service Line Installation Date	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field Verified:		Customer-Owned Portion Service Line Material Classification	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field Verified:		
														Describe the Field Verification Method	Enter the Date of Field Verification				Describe the Field Verification Method	Enter the Date of Field Verification	
2038	N/A	1001	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
2039	N/A	1005	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
2040	N/A	1009	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
2041	N/A	1013	19TH	STREET	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
2042	N/A	1720	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2043	N/A	1724	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2044	N/A	1724	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2045	N/A	1728	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2046	N/A	1919	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2047	N/A	1919	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2048	N/A	2001	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
2049	N/A	2001	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
2050	N/A	2001	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
2051	N/A	2002	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
2052	N/A	2003	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
2053	N/A	2004	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2054	N/A	2005	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
2055	N/A	2008	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
	N/A	2009	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
2056	N/A	2011	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
2057	N/A	2012	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Unknown - Material Unknown		No			
2058	N/A	2015	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
2059	N/A	2016	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2060	N/A	2017	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
2061	N/A	2019	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
2062	N/A	2020	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
2063	N/A	2021	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2064	N/A	2022	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2065	N/A	2024	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	No			
2066	N/A	2025	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2067	N/A	2026	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
2068	N/A	2028	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
2069	N/A	2029	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
2070	N/A	2031	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
2071	N/A	2033	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
2072	N/A	2101	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
2073	N/A	2102	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
2074	N/A	2106	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	No			
2075	N/A	2114	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
2076	N/A	2115	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
2077	N/A	2127	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
2078	N/A	2219	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
2079	N/A	2222	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	No			
2080	N/A	2223	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
2081	N/A	2226	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
2082	N/A	2227	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
2083	N/A	2234	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
2084	N/A	2235	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
2085	N/A	2238	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
2086	N/A	2239	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Unknown - Material Unknown		No			
2087	N/A	2242	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Galvanized	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
2088	N/A	2246	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			copper	Other	Yes	Visual inspection at the meter pit	2019	
2089	N/A	2247	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Galvanized	Other	Yes	Visual inspection at the meter pit	2019	
2090	N/A	2251	19TH	AVENUE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Unknown - Material Unknown		No			

































Unique Service Line ID	Lead and Copper Sample Site #	Street Address			High-Risk or Sensitive Population? (Yes/No)	Classification of Entire Service	Was a Lead Service Line Previously Replaced at this Location?	Material of Service Line Replacement	Is Service Line newly Identified Since Last Submitted Inventory?	System-Owned Portion (Main to B-Box)							Customer-Owned Portion (B-Box to Meter)				
										System-Owned Portion (Main to B-Box) Service Line Material Classification	Service Line Installation Date	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field Verified:		Customer-Owned Portion Service Line Material Classification	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field Verified:		
														Describe the Field Verification Method	Enter the Date of Field Verification				Describe the Field Verification Method	Enter the Date of Field Verification	
2847	N/A	800	VILLAGE	SQUARE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2848	N/A	800	VILLAGE	SQUARE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2849	N/A	900	VILLAGE	SQUARE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2850	N/A	900	VILLAGE	SQUARE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2851	N/A	900	VILLAGE	SQUARE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2852	N/A	1000	VILLAGE	SQUARE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2853	N/A	1000	VILLAGE	SQUARE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2854	N/A	3000	VILLAGE	SQUARE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2855	N/A	3000	VILLAGE	SQUARE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2856	N/A	4000	VILLAGE	SQUARE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
2857	N/A	4000	VILLAGE	SQUARE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Copper	Other	Yes	Visual inspection at the meter pit	2019	
2858	N/A	5000	VILLAGE	SQUARE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2859	N/A	5000	VILLAGE	SQUARE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2860	N/A	6000	VILLAGE	SQUARE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2861	N/A	6000	VILLAGE	SQUARE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2862	N/A	6000	VILLAGE	SQUARE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2863	N/A	7000	VILLAGE	SQUARE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2864	N/A	7500	VILLAGE	SQUARE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2865	N/A	7500	VILLAGE	SQUARE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2866	N/A	7550	VILLAGE	SQUARE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2867	N/A	7700	VILLAGE	SQUARE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2868	N/A	8000	VILLAGE	SQUARE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	
2869	N/A	8000	VILLAGE	SQUARE	No	Unknown	No	N/A	No	Unknown - Material Unknown	Unknown	Other	No			Iron	Other	Yes	Visual inspection at the meter pit	2019	